

ТОУОТА					
XRS-RJ45W1 / XRS-RJ45R1"		XRS-RJ45W2 / XRS-RJ45R2			
FJ Cruiser (2011 - 2016) *Roof Console only	Tacoma (2012 - 2018) *Left hand side of steering wheel (LHD)	FJ Cruiser (2007 - 2018)	Landcruiser 70 Series *Plastic Dash		
Hilux (9/2015 - Current)	Highlander (2001 - 2018)	Fortuner (2005 - 2015)	Landcruiser 79 (2021-Current) *Centre Console		
Landcruiser 79 (2021-Current) *Right hand side of steering wheel	4Runner (2010 - 2014)	Hiace (2005 - 2013)	4Runner (2003 - 2009)		
Landcruiser 200 (2008 - 2021)	Fortuner (2016 - Current)	Hilux (2005 - 2015)	Kluger (2001 - 2007)		
Prado 150 (2010 - 2018) *2018 onwards only on left hand side of steering wheel	Hiace (2014 - 2018)	Landcruiser 100 (1998 - 2007)	Prado 120 (2003 - 2009)		
RAV4 (2006 - 2018)	Kluger (2008 - 2018)	Tacoma (2005-2022)	Tundra (2005-2007) *Centre Console		
Tacoma (2016 - 2022)					

^{**}Ford Rangers and Holden Colorado require an aftermarket fascia to install additional switches and adaptors. Common aftermarket fascia available use the Type 1 (XRS-RJ45W1 or XRS-RJ45R1) style adaptor.

These fascia are NOT sold through GME.



ТОУОТА					
XRS-RJ45T5		XRS-RJ45W10 / XRS-RJ45R10	XRS-RJ45W11 / XRS-RJ45R11		
Prado 150 (2018 - Current)	Kluger (12/2019 - Current)	Landcruiser 79 (2021 - Current)	Landcruiser 70 Series (2024 – Current) *Air Con Panel		
Prado 250 (2024-Current)	Landcruiser 300 (2022 - Current)		Landcruiser 70 Series (2009 – 2023) *Air Con Panel		
RAV4 (6/2019 - Current)	Landcruiser Face-lift 70 Series (2024 - current) *Center Console		Landcruiser 70 Series (Horizontal) (1984 – 2009)		
Hiace (5/2019 - Current)	Tacoma (2024 - Current)		Landcruiser 80 Series (Horizontal) (1990 – 1997)		
Camry (2018 - Current)	Tundra (2022 - Current)		Hilux (1993 – 1997)		



NISSAN		ISUZU
XRS-RJ45W3 / XRS-RJ45R3	XRS-RJ45W8 / XRS-RJ45R8	XRS-RJ45W4 / XRS-RJ45R4
Patrol GU Series 4-8 (2004 - 2018)	Navara NP300 (2016 - Current)	D-Max 2nd Generation (2012 - 2020) *Lower Switch Fascia under A/C Controls where fitted
Patrol Y62 (2016 - Current)	Pathfinder R52 (2012 - 2020)	MU-X 1st Generation (2012 - 2021) *Lower Switch Fascia under A/C Controls where fitted
X-Trail T31 (2007 - 2014)	X-Trail T32 (2014 - 2022)	
Pathfinder R51 (2005 - 2012)		
Navara D40 (2008 - 2014)		
Navara NP300 (2016 - Current) *Handbrake Console		



ISUZU / MAZDA	MITSUBISHI	UNIVERSAL	
XRS-RJ45T7	XRS-RJ45W9 / XRS-RJ45R9	XRS-RJ45RND	XRS-RJ45W6 / XRS-RJ45R6
BT-50 3rd Generation (10/2021 - Current)	Triton MQ (2015 - 2018)	Universal Fitment into a 25mm Round Hole	Suits Carling Style Dash Hole Dimensions
D-Max 3rd Generation (9/2021 - Current)	Triton MR (2019 - 2023)	24.7 30	RJ45 Type 6 26.3 39.8
MU-X 2nd Generation (2022 - Current) *Models without heated seats	Pajero Sport KR, KS, QE (2015 - 2021)		
Outlander ZK (2012 - 2021)	39.8		